

Translated version from Kannada Language to English Language

GOVERNMENT OF KARNATAKA

Office of the Executive Engineer
No.2nd Buildings Section, K. R. Circle,
Bengaluru

Telephone 22122856, Fax 080-22123368
e-mail eebldno2@gmail.com

PUBLIC WORKS DEPARTMENT

No. EEE:BD-2:2Im-6:22-23/185

Date: 02/03/2023

To,
The Secretary/ President,
Soundarya Educational Trust (Regd.),
Havanoor Layout, Hesaraghatta Main Road,
Bengaluru -560073.



Respected Sir/ madam,

Subject	Regarding to Issue Building Safety Certificate.
Reference	1) Letter of your Office dated: 15-02-2023, 2) Letter of Office of the Assistant Executive Officer, No.9 th Buildings Sub Division, Bengaluru in No.608:A; dated: 22-02-2023.


With respect to the above said subject, Soundarya School, Havanoor Layout, Hesaraghatta Main Road, Bengaluru run by Educational Charity Soundarya Educational Trust (Regd.,) have requested to issue Building Safety Certificate in Application as referred to above vide Reference (1) above.

Likewise, Inspection of the spot was conducted on 22-02-2023 in presence of the Assistant Executive Officer, No.9th Buildings Sub Division, Bengaluru along with concerned documents with respect to the school building, has subjected the following explanations vide Reference (2) above.

• The Joint Inspection of the building of Soundarya School, Havanoor Layout, Hesaraghatta Main Road, Bengaluru was conducted on 22-02-2023.

• The building consists of upper 4 Floors, the steps and toilet facility has been constructed as per guidelines. And drinking water facility has been furnished.

.....2/-



- The Building Completion Certificate was obtained by BBMP.
- The Principal of the School has certified that the Building Plan and Sketch were issued and the building was constructed as per the said Plan and Sketch.
- The strength of the concrete for the stability of the building was inspected through Karnataka Test House, Pvt Ltd and the said Karnataka Test House, Pvt Ltd has certified through its Technical Manager that the building is stable.
- The place of the said building is subject to the jurisdiction of Zone-V Division.

After verifying all the document furnished by the said Institution, by considering the certificate issued by "Karnataka Test House, Pvt Ltd" as the BUILDING IS CONSTRUCTIVELY SAFE, and when the building was inspected by Technical Team of Public Works Department, it is found from the Inspection Reports that the building "Structurally Stable" the NO OBJECTION CERTIFICATE for the year 2022-23 was issued as the said building is "Structurally Stable" after spot verification conducted on 23-02-2023.

Your Faithfully,

Sd/-

Executive Engineer,

No.2nd Buildings Section, K. R. Circle, Bengaluru.



TRANSLATED & VERIFIED BY ME

K.V. RAMASANJEEVAIAH
B.A.L.L.B.

Advocate & Notary Public
GOVT. OF INDIA
37, 4th Cross, 1 Main
Siddeshwara Layout, Siddeshwara,
Nagasandra Post, BENGALURU - 560 073

GOVT. OF KARNATAKA
HAS DISCONTINUED THE
USE OF NOTARIAL STAMPS W.E.F. 01-04-2003

26 JUN 2023





ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂಖ್ಯೆ : ಕಾಪಾಅ:ಕವಿ-2:2ಇಂ-6:22-23/185

ದಿನಾಂಕ : 02/03/2023

ಇವರಿಗೆ,

ಕಾರ್ಯದರ್ಶಿಗಳು : ಅಧ್ಯಕ್ಷರು,
ಸೌಂದರ್ಯ ಎಜುಕೇಷನಲ್ ಟ್ರಸ್ಟ್ (ರಿ)
ಹಾವನೂರು ಬಡಾವಣೆ, ಹೆಸರಘಟ್ಟ ಮುಖ್ಯ ರಸ್ತೆ,
ಬೆಂಗಳೂರು - 560 073.

ಮಾನ್ಯರೇ,

ವಿಷಯ	ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ
ಉಲ್ಲೇಖ	1) ತಮ್ಮ ಕಛೇರಿ ಪತ್ರ ದಿನಾಂಕ : 15-02-2023 2) ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.9ನೇ ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು ರವರ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ:608/ಎ/ದಿನಾಂಕ 22-02-2023.


ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸೌಂದರ್ಯ ಎಜುಕೇಷನಲ್ ಟ್ರಸ್ಟ್ (ರಿ) ವಿದ್ಯಾ ದತ್ತಿಯಿಂದ ನಡೆಸುತ್ತಿರುವ ಸೌಂದರ್ಯ ಸ್ಕೂಲ್, ಹಾವನೂರು ಬಡಾವಣೆ, ಹೆಸರಘಟ್ಟ ಮುಖ್ಯ ರಸ್ತೆ, ಬೆಂಗಳೂರು ರವರು ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವಂತೆ ಉಲ್ಲೇಖ (1)ರ ಪತ್ರದಲ್ಲಿ ಕೋರಿಯುತ್ತೀರಿ.

ಅದರಂತೆ, ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ಸಂಬಂಧಪಟ್ಟ ದಾಖಲೆಗಳೊಂದಿಗೆ ದಿನಾಂಕ 22-02-2023ರಂದು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.9ನೇ ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ ರವರ ಉಪಸ್ಥಿತಿಯಲ್ಲಿ ಸ್ಥಳ ಪರಿಶೀಲಿಸಿ, ಈ ಕೆಳಕಂಡಂತೆ ವಿವರಣೆಗಳನ್ನು ಉಲ್ಲೇಖ (2)ರ ಪತ್ರದಲ್ಲಿ ಸಲ್ಲಿಸಿರುತ್ತಾರೆ.

- ಸೌಂದರ್ಯ ಸ್ಕೂಲ್, ಹಾವನೂರು ಬಡಾವಣೆ, ಹೆಸರಘಟ್ಟ ಮುಖ್ಯ ರಸ್ತೆ, ಬೆಂಗಳೂರು ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ 22-02-2023 ರಂದು ಜಂಟಿ ಪರಿವೀಕ್ಷಣೆ ಕೈಗೊಳ್ಳಲಾಗಿರುತ್ತದೆ.
- ಕಟ್ಟಡವು ನೆಲಮಹಡಿ ಹಾಗೂ 4 ಮೇಲ್ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಿದ್ದು, ಸದರಿ ಕಟ್ಟಡದಲ್ಲಿ ಮೆಟ್ಟಿಲುಗಳನ್ನು ಹಾಗೂ ಶೌಚಾಲಯದ ವ್ಯವಸ್ಥೆಯನ್ನು ಮಾರ್ಗಸೂಚಿಯನ್ವಯ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ. ಮತ್ತು ಕುಡಿಯುವ ನೀರಿನ ವ್ಯವಸ್ಥೆ ಕಲ್ಪಿಸಲಾಗಿರುತ್ತದೆ.
- ಕಟ್ಟಡವು ಪೂರ್ಣಗೊಂಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಪತಿಯಿಂದ ಪಡೆಯಲಾಗಿರುತ್ತದೆ.
- ಕಟ್ಟಡದ ನಕ್ಷೆ ಹಾಗೂ ವಿನ್ಯಾಸದ ನಕ್ಷೆಗಳನ್ನು ನೀಡಿದ್ದು, ಅದರಂತೆ ಕಟ್ಟಡವನ್ನು ನಿರ್ಮಿಸಲಾಗಿದೆ ಎಂದು ಶಾಲೆಯ ಪ್ರಾಂಶುಪಾಲರು ಧೃಢೀಕರಿಸಿರುತ್ತಾರೆ.
- ಕಟ್ಟಡದ ಸ್ಥಿರತೆಗಾಗಿ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯನ್ನು (Karnataka Test House, Pvt Ltd) ಪತಿಯಿಂದ ಪರಿಶೀಲಿಸಿ ಪಡೆಯಲಾಗಿದ್ದು, ಕಟ್ಟಡವು ಸದೃಢವಾಗಿರುವುದಾಗಿ ಸದರಿ ಕರ್ನಾಟಕ ಟೆಸ್ಟ್ ಹೌಸ್ ಪ್ರೈವೇಟ್ ಲಿಮಿಟೆಡ್, Technical Manager ರವರಿಂದ ಧೃಢೀಕರಿಸಲಾಗಿರುತ್ತದೆ.
- ಸದರಿ ಕಟ್ಟಡದ ಸ್ಥಳವು Zone-IV ವಿಭಾಗಕ್ಕೆ ಒಳಪಟ್ಟಿರುತ್ತದೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ "Karnataka Test House, Pvt Ltd" ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ, ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡ ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡವು "Structurally Stable" ಇರುವುದಾಗಿ ಪರಿಶೀಲನೆ ಪರದಿಗಳಿಂದ ಕಂಡು ಬಂದಿರುವುದರಿಂದ ದಿನಾಂಕ 23-02-2023 ರಂದು ಸ್ಥಳ ಪರಿವೀಕ್ಷಿಸಲಾಗಿ ಸದರಿ ಕಟ್ಟಡವು "Structurally Stable" ಇದೆ ಎಂದು ನಿರಾಕ್ಷೇಪಣಾ ಪತ್ರವನ್ನು 2022-23ನೇ ಸಾಲಿಗೆ ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸ


ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

ನಂ. 2ನೇ ಕಟ್ಟಡಗಳ ವಿಭಾಗ, ಬೆಂಗಳೂರು.



